

DRIVER'S VEHICLE POST-TRIP INSPECTION REPORT

CARRIER: Northgate Gonzalez LLC

LOCATION: Anaheim CA

Submission Date 3/10/2026 10:45 AM

Tractor 45 **Odometer Out** 543 **Odometer In**

Air Compressor Post-Trip

Air Lines Post-Trip

Battery Post-Trip

Belts and Hoses

Body

Brake Accessories

Brakes, Parking

Brakes, Service

Clutch

Coupling Devices

Defroster/Heater

Drive Line

Engine

Exhaust

Fifth Wheel

Fluid Level

Frame an Assembly

Front Axel

Fuel Tanks

Generator

Horn

Lights Head - Stop - Tail - Dash - Turn Indicators

Mirrors

Muffler

Oil Level

Radiator Level

Rear End

Reflectors

Safety Equipment Fire Extinguisher - Flag - Flares - Fuses - Reflective Triangles - Spare Bulbs and Fuses - Spare Seal Beam

Starter

Steering

Suspension System

Tire Chains

Tires

Transmisson

Trip Recorder

Wheels and Rims

Windows

Windshield Wipers

Other

TRAILOR NO.1

TRAILOR NO.2

Brake Connections

Brakes

Coupling Devices

Coupling (King) Pin

Doors

Hitch

Landing Gear

Lights - All

Reflectors/Reflective Tape

Roof

Suspension System

Straps

Tarpaulin

Tires

Wheels and Rims

Other

Remarks test

Driver Employee Number 30848

Driver Name Mercado, Gabriel

No Image