

DRIVER'S VEHICLE PRE-TRIP INSPECTION REPORT

CARRIER: Northgate Gonzalez LLC

LOCATION: Anaheim CA

Submission Date 3/10/2026 11:00 AM

Tractor 46 Odometer Out Odometer In

Air Compressor Pre-Trip

Air Lines Pre-Trip

Battery Pre-Trip

Belts and Hoses

Body

Brake Accessories

Brakes, Parking

Brakes, Service

Clutch

Coupling Devices

Defroster/Heater

Drive Line

Engine

Exhaust

Fifth Wheel

Fluid Level

Frame an Assembly

Front Axel

Fuel Tanks

Generator

Horn

Lights Head - Stop - Tail - Dash - Turn Indicators

Mirrors

Muffler

Oil Level

Radiator Level

Rear End

Reflectors

Safety Equipment Fire Extinguisher - Flag - Flares - Fuses - Reflective Triangles - Spare Bulbs and Fuses - Spare Seal Beam

Starter

Steering

Suspension System

Tire Chains

Tires

Transmisson

Trip Recorder

Wheels and Rims

Windows

Windshield Wipers

Other

---

TRAILOR NO.1   TRAILOR NO.2

Brake Connections

Brakes

Coupling Devices

Coupling (King) Pin

Doors

Hitch

Landing Gear

Lights - All

Reflectors/Reflective Tape

Roof

Suspension System

Straps

Tarpaulin

Tires

Wheels and Rims

Other

Remarks

Driver Employee Number   30848

Driver Name                      Mercado, Gabriel

No Image