

DRIVER'S VEHICLE PRE-TRIP INSPECTION REPORT

CARRIER:	Northgate Gonzalez LLC		
LOCATION:	Anaheim CA		
Submission Date	3/13/2026 3:28 PM		
Tractor	46	Odometer Out	130 Odometer In
Air Compressor			Pre-Trip
Air Lines			Pre-Trip
Battery			
Belts and Hoses			
Body			
Brake Accessories			
Brakes, Parking			
Brakes, Service			
Clutch			
Coupling Devices			
Defroster/Heater			
Drive Line			
Engine			
Exhaust			
Fifth Wheel			
Fluid Level			
Frame an Assembly			
Front Axel			
Fuel Tanks			
Generator			
Horn			
Lights Head - Stop - Tail - Dash - Turn Indicators			
Mirrors			
Muffler			
Oil Level			
Radiator Level			
Rear End			
Reflectors			
Safety Equipment Fire Extinguisher - Flag - Flares - Fuses - Reflective Triangles - Spare Bulbs and Fuses - Spare Seal Beam			
Starter			
Steering			
Suspension System			
Tire Chains			
Tires			
Transmisson			

Trip Recorder
Wheels and Rims
Windows
Windshield Wipers
Other

TRAILOR NO.1 TRAILOR NO.2

Brake Connections
Brakes
Coupling Devices
Coupling (King) Pin
Doors
Hitch
Landing Gear
Lights - All
Reflectors/Reflective Tape
Roof
Suspension System
Straps
Tarpaulin
Tires
Wheels and Rims
Other

Remarks test

Driver Employee Number

Driver Name Call, Will

No Image